


FRONT SHOCK ABSORBER INSPECTION

1. INSPECT FRONT SHOCK ABSORBER



- a. Compress and extend the shock absorber rod 4 or more times.

Standard

There is no abnormal resistance or sound and operation resistance is normal.

Tech Tips

If there is any abnormality, replace the front shock absorber with a new one.